



Suspended Loads

General Rules

- All personnel are to be clear of the load and do not stand or walk under the load at any time.
- Plan lifting operations to minimize or eliminate swinging loads over workers.
- Check for any overhead obstructions such as overhangs and power lines.
- Good load control requires the use of a tag line.
- Never leave a suspended load unattended.
- Always wear a hard hat.



Do not walk under a suspended load

You should...

- Never cross a barrier controlling an area with a suspended load without authorization
- Follow the instructions of the Flagman or the Person in Charge of the lift

A Person in Charge should...

- Mark the unsafe area and put barriers in place
- Ensure that nobody walks under a suspended load



